Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: **Monument No. 1**Mine ID: **246**

Navajo AUM North Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.039.0020

April 2012

Part I	Site Identification, Location and Status				
Site Names an	nd ID numbers	s as applicable			
Mine ID:	246				
Map ID:	NC41				
CERCLIS:	NNN0009092	66			
Navajo Aban	doned Mine La	and Reclamati	on Program: NA-02	210	
Local name /	Aliases: Origin	nal Monument	No. 1 Mine; Monume	ent-1 (Old); Monument #1 - A	
Chapter and	local area: Olj	jato			
County: Nav	ajo	State:	AZ		
Lat/Long:	36.9478156688 N / -110.231183789 W				
Nearby road	and highway:	Route 163	Local Post Office:	Oljato, AZ	
Surface Land below	Status: check	one or more a	and provide ownersh	ip and contact information	
Tribal Trust Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land		
Subsurface Mineral Rights:					
No informatio	n on subsurface	e mineral rights	ownership was found	I in the EPA/AUM Database.	
Claim and op	erator inform	ation:			
Historical doc	uments identifi	ed the operator	of the mine from 194	2 to 1950 as Vanadium	

Number of residential structures within 200 feet of mine: None

the EPA / AUM database.

Corporation of America. No additional historical ownership / lease information was identified in

Part II Summary of Radiological Readings

Mine ID: 246

Highest gamma radiation measurement: 445,500 counts per minute (cpm)


Background Average: 12,655 cpm **Two Times Background:** 25,310 cpm

Describe any other radiological measurements:

A total of 2,849 gamma radiation measurements were collected from the mine site, ranging from 6,820 cpm to 445,500 cpm. Maximum levels of approximately 450,000 cpm were found in the vicinity of the waste rock and 20,000 cpm were found near the adit. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics				
Number of Readings	2,849			
Minimum (cpm)	6,820			
Maximum (cpm)	445,500			
Mean (cpm)	22,323			
Median (cpm)	15,589			
Standard Deviation	24,313			



Part III Status of Reclamation and Mine Waste

Mine ID: 246

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0210

NAMLRP Mine features: 1 Prospect; 2 Portals

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits:

1 adit, concrete cinderblock sealed, approximately 8' wide x 3.5' high

Waste Piles:

Scattered waste rock along cliff face

Pits:

None Observed

Shafts:

None Observed

Other Debris and Mine Features:

Central reclamation cap with erosional cuts; mining debris at south end of site

Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None Observed

200 feet to 0.25 mile: None Observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: None Observed

0.25 miles to 4 miles: 3.5 mi W - Water Well 8K-433; 4 mi SW - Well (519)

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Monument No. 1 mine claim consists of an area of 37,316 m². The mine was identified as being operational from 1942 to 1953. While operational, the mine had a total reported production volume of 4,164 tons. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity?

Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? Yes

Structures:

Were any structures observed within 200 feet of the mine? $\ensuremath{\mathrm{No}}$

Potential Drinking Water Sources:


Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?


Yes

Part VI Photos




















Part VII Contact Reports and Information

Name:	Eugene Esplain		
Title or official role (if any):	Navajo EPA Superfund Program		
Telephone number:	(928) 871-7331		
Address:	PO Box 2946, Window Rock, AZ 86515		
Information provided:	Lead Regulatory Agency		
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Monument No. 1 (246)
Oljato Chapter, Navajo Nation



Gamma Radiation Measurements

- < 2X Backgound</p>
- > 2X Background

Measured as counts per minute (cpm)

Average background 12,655 cpm



General Slope Direction

Observed Reclamation Feature













Figure 2 - Gamma Radiation Measurements Monument No. 1 (246) Oljato Chapter, Navajo Nation




Gamma Radiation Measurements

- 0 10,000 cpm
- 10,000 25,000 cpm
- 25,000 50,000 cpm
- 50,000 100,000 cpm
- 100,000 250,000 cpm
- 250,000 500,000 cpm
- 500,000 1,000,000 cpm

Mine Site Boundary

General Slope Direction

Observed Reclamation Feature



Observed Adit

Measured as counts per minute (cpm)



Average background 12,655 cpm